

LOCAL FIREHALL

ID: 9590



PROBLEM

Rebar was being attacked by moisture and causing it to spall.

APPLICATION SITUATION

Concrete would have taken longer to cure and not offered the same properties as Belzona 4111.

APPLICATION METHOD

Angle grinder, trowels and sanding discs were used to prep and apply

BELZONA FACTS

Belzona was able to do this repair faster and use a more reliable product than any of the other options.

INDUSTRY

Buildings & Structures

LOCATION

Abbotsford BC

APPLICATION DATE

June 2022

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Before repainting the firehall the customer needed to make sure that the walls were repaired.
2. All loose areas were removed.
3. After patching the area using Belzona 4111 magma quartz an angle grinder and sanding disc were used to achieve smoothness and a good transition between the old and new coating.
4. Once smoothed out, the area was left for the painting crew to repaint.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

