

BELZONA REPAIRS EXPANSION JOINT LEAK

ID: 9592



PROBLEM

Holes in an acid tank expansion joint needed to be repaired without welding.

APPLICATION SITUATION

Emergency repair on exp joint was required without welding. Belzona and quick curing elastomers were used safely and successfully.

APPLICATION METHOD

Area cleaned and neutralized, conditioner applied followed by elastomer with reinforcement cloth.

BELZONA FACTS

Without the ability to weld belzona was the only option. Quick application made for short work and back in operation quickly.

INDUSTRY

Steel & Metal Processing

LOCATION

Trail

APPLICATION DATE

May 2024

PRODUCTS

Belzona 2311 (SR Elastomer)

Belzona 2911 (Elastomer QD Conditioner)

SUBSTRATE

Stainless-steel

PHOTOS

1. Holes found
2. Preparation completed
3. Belzona elastomer and cloth applied
4. The bespoke application crew!

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](https://www.khia.belzona.com)

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

