

REPAIR OF THE DAMAGED WALL AND BOTTOM OF THE BOILER CONDENSATION CONTAINER

ID: 9600



PROBLEM

When using the Buderus condensing boiler, the bottom and walls of the boiler were damaged by corrosion.

APPLICATION SITUATION

Corrosion caused damage to the bottom and walls of the boiler, making further use impossible.

APPLICATION METHOD

Abrasive surface treatment, desalination, degreasing and inspection before application. Repair of the outlet thread.

Application of the protective system with the material Belzona 1511 and 1593.

BELZONA FACTS

If the customer does not want to replace the damaged part, then it had to be repaired. Repair and protection with Belzona products was significantly cheaper than replacing with a new part.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

Slovakia

APPLICATION DATE

August 2021

PRODUCTS

Belzona 1511 (Super HT-Metal)
Belzona 1593

SUBSTRATE

Carbon steel

PHOTOS

1. Damaged bottom and walls of the boiler.
2. The surface of the damaged bottom and wall of the boiler had to be blasted before applying Belzona products.
3. The missing original material was supplemented with the Belzona 1511 product.
4. Both the bottom and the walls were treated with the product Belzona 1593.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

