

BELZONA RESTORED AND PROTECTED THE OIL SEALING SURFACE OF WIND TURBINE

ID: 9607



PROBLEM

The oil sealing surface of a wind turbine at the wind farm were worn out and needed to be repaired.

APPLICATION SITUATION

The operating temperature was ambient. Wind farms were very windy and the sealing surface of the wind turbine was heavily abraded.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How leaflets FBC-05. Surface preparation was carried out by grinding with an angle grinder, followed by repair and protection of the sealing surfaces with Belzona 1311.

BELZONA FACTS

After four months of use, no leaks were seen in the inspection and the client was very satisfied with the results. This solution greatly reduced the cost of replacement for the client, as well as downtime.

INDUSTRY

Power

LOCATION

Yunnan, China

APPLICATION DATE

August 2023

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

SUBSTRATE

Carbon steel

PHOTOS

- 1. Full view of wind turbine
- 2. Sealing face before repair
- 3. During application
- 4. Application finished

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

