

PROTECTION OF THE BOTTOM OF THE TANK AGAINST CORROSION

ID: 9608



PROBLEM

Damage appeared on the bottom of the tank due to corrosion.

APPLICATION SITUATION

Corrosion causes damage to the bottom of the tank and contamination of the processed product.

APPLICATION METHOD

Surface blasting to Sa 2.5 with a profile of 75 µm. Surface degreasing. Application of the product Belzona 1391 T in two layers with a total thickness of approx. 900 µm. Curing of material

BELZONA FACTS

The customer needed a fast and high-quality solution at a good price.

INDUSTRY

Chemical & Petrochemical

LOCATION

Slovakia

APPLICATION DATE

May 2022

PRODUCTS

Belzona 1391T

SUBSTRATE

Carbon steel

PHOTOS

1. Detail of blasting.
2. Blasted tank bottom.
3. Application of the product Belzona 1391 T in two layers.
4. General view of the tank

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

