

REPAIR OF WELDS IN STAINLESS STEEL GUTTER.

ID: 9609



PROBLEM

The welds started to crack in the stainless steel gutter.

APPLICATION SITUATION

Repair of welds by conventional welding would be lengthy, it would be necessary to thoroughly clean the places. Also, changing the gutters was out of the question due to time.

APPLICATION METHOD

Blasting of local places - welds. Cleaning + vacuuming + degreasing. Gap filling with Belzona 1511. Application of Belzona 1983 SuperWrap II + 9381.

BELZONA FACTS

Repair with Belzona products is the fastest and most effective. The quality of the repair was also at a high level.

INDUSTRY

Chemical & Petrochemical

LOCATION

Slovakia

APPLICATION DATE

September 2023

PRODUCTS

Belzona 1511 (Super HT-Metal)
Belzona SuperWrap II

SUBSTRATE

Stainless-steel

PHOTOS

1. Damages in the gutter were detected with a test spray.
2. Cracks on the bottom of the gutter.
3. Replacement of original material with Belzona 1511 product.
4. Wrap and reinforce with Belzona 1983 SuperWrap II + 9381 products.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

