

LINING OF A YACHT'S DIESEL TANKS

ID: 9645



PROBLEM

Two tanks that have been converted from ballast to diesel required lining at the base. The tanks covered 50 m² in total.

APPLICATION SITUATION

Belzona provided a long-term solution for meeting client expectations.

APPLICATION METHOD

Before 1311 was applied to the substrate after it was grit blasted. The lining material was Belzona 1321.

BELZONA FACTS

Belzona offered a protection to the tanks.

INDUSTRY

Marine

LOCATION

Spanopoulos Shipyard (Salamina)

APPLICATION DATE

October 2024

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Yacht external view at the shipyard
2. Application of Belzona 1311 to rebuild pitted areas
3. Application of Belzona 1321 on top of Belzona 1311
4. Finished job

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

