

BELZONA 1111 FOR FLANGE FACE REPAIR

ID: 9659



PROBLEM

Worn-out flange face needs to be repaired

APPLICATION SITUATION

The repair was completed in one day, allowing the equipment to be back in service on the next day.

With Belzona solution, the asset owner can minimize downtime and maximize efficiency of the equipment.

APPLICATION METHOD

Using the forming technique to apply Belzona 1111 (Super Metal) to achieve a seamless, high-performance repair.

BELZONA FACTS

Thanks to Belzona 1111 (Super Metal), the asset owner can continue operation without the need to change the flange.

INDUSTRY

Oil & Gas

LOCATION

Saudi Arabia

APPLICATION DATE

February 2021

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Worn-out flange face need repair
2. Forming technique was used to rebuild the flange face
3. Flange face was successfully restored and ready for service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

