

BELZONA DRAIN COVERS

ID: 966



PROBLEM

Existing covers and surrounds badly deteriorated due to corrosion and chemical attack. rapid solution required due to continuous production schedule on site. Conventional steel/concrete covers do not have adequate resistance.

APPLICATION SITUATION

Deterioration of drain covers and surrounds

APPLICATION METHOD

Application was carried out in accordance with a modified Belzona Know-How System Leaflet FPA-1. New drain covers were manufactured off-site from Stainless Steel and infilled with Belzona® 4111. On site bedded into Belzona® 4111 and damaged surrounds rebuilt.

BELZONA FACTS

The work was carried out during the agreed window in a professional manner with no disruption to the production processes. Solution provides long term solution.

INDUSTRY

General Industry

LOCATION

Bakery, West Midlands, UK

APPLICATION DATE

May 2008

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Stainless Steel

PHOTOS

1. Fabricated drain covers in Steel being conditioned
2. Bulk out Belzona 4111 being applied
3. Bulk out Belzona 4111 finished ready to be topped off with Belzona 4111
4. Finished cover ready for transport and installation on site

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

