

COOLING WATER HEAD BROUGHT BACK TO LIFE WITH BELZONA 1391T

ID: 9661



PROBLEM

Customer pulled several HEX for routine inspections and discovered bad pitting on one the Cooling Water Heads. They were in a small Pit-Stop and had 3 days to get this repaired and back in service.

APPLICATION SITUATION

This was an emergency for the customer as they could not restart this unit without their cooling water HEX. We were able to load the head and take it to our shop. Blast and coat and return in 24 hours.

APPLICATION METHOD

We blasted and filled pitting with 1111, coated with 2 coats of 1391T.

BELZONA FACTS

Save the customer thousands of dollars by getting this back and not delaying the startup process.

INDUSTRY

Oil & Gas

LOCATION

Texas

APPLICATION DATE

January 2018

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1391T

SUBSTRATE

Carbon steel

PHOTOS

1. Cooling Water Head Before
2. Cooling Water Head After

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

