

BELZONA 3131 LONG TERM ROOF PROTECTION

ID: 9664



PROBLEM

Two large roofs were experiencing leaks due to ageing mineral felt. This was causing issues to the operations inside the buildings.

APPLICATION SITUATION

By using a liquid applied membrane these roof sections could be made watertight whilst minimising disruption to the operations on the treatment works.

APPLICATION METHOD

The roofs were first power washed, treated with fungicide. Two coats of Belzona 3131 WG Membrane were then applied.

BELZONA FACTS

The 3131 WG Membrane minimised the potential for weather disruptions. It also had the benefit of being applied direct to felt without the need for a conditioner.

INDUSTRY

Water / Wastewater

LOCATION

Scotland

APPLICATION DATE

July 2020

PRODUCTS

Belzona 3131 (WG Membrane)

SUBSTRATE

Other

PHOTOS

- 1. Belzona 3131 application
- 2. Application underway
- 3. Roof section after 4 years service
- 4. Still in excellent condition

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

