



CONCRETE STAIRS SAVED FROM FURTHER DILAPIDATION.

ID: 9696



PROBLEM

Stairs was experiencing cracks along the railing pillar and was on the verge of falling apart.

APPLICATION SITUATION

Concrete stairs was on the verge of falling apart due to stress from the railings and customer wanted a fast repair that would enable the area opened to the public in the fastest way.

APPLICATION METHOD

The weak parts of the concrete stairs was removed and vacuumed. The areas were subsequently rebuilt with Belzona 4111.

BELZONA FACTS

Belzona repair was carried out and the area opened to for public use in matter of days.

INDUSTRY

Local Authorities & Municipalities

LOCATION

Ontario

APPLICATION DATE

September 2014

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Cracks on stairs before repair.
2. Further cracks .
3. After surface preparation.
4. Stairs after repair.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

