

GAYLORD OPRYLAND EXPANSION JOINT

ID: 9699



PROBLEM

Customer had a failing expansion Joint. It was also a trip hazard.

APPLICATION SITUATION

Belzona was a great solution.

APPLICATION METHOD

Old failing joint was removed, and the joint was cleaned out. Tape was used to keep a straight line.

BELZONA FACTS

Customer has used Belzona in the past and trust the outcome.

INDUSTRY

Buildings & Structures

LOCATION

Nashville

APPLICATION DATE

June 2023

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 2941 (Elastomer SP-Conditioner)

SUBSTRATE

Masonry

PHOTOS

1. Expansion joint before application
2. Application of Belzona 2211
3. Application completed with Belzona 2211

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.