

BELZONA PROTECTS PAPER MACHINE FILTER

ID: 97



PROBLEM

Severe corrosion including some small holes, due to soda concentration in the paper.

APPLICATION SITUATION

Stainless steel filter on large paper machine

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets TCC-1 & TCC-5. Belzona® 1111 used to seal holes before surface protected from further corrosion by coating with Belzona® 1321.

BELZONA FACTS

Belzona application allowed paper production to continue without further interruptions.

INDUSTRY

Pulp & Paper

LOCATION

Paper Mill in France

APPLICATION DATE

August 1991

PRODUCTS

Belzona 1111
Belzona 1321

SUBSTRATE

Stainless steel

PHOTOS

1. General view of the filter
2. Application of Belzona 1321 underway
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

