

HOSPITAL DRAIN

ID: 9706



PROBLEM

Drain was leaking in patients room.

APPLICATION SITUATION

Customer was planning on replacing the concrete and drain before I gave them the option to repair it.

APPLICATION METHOD

Concrete was prepared with hand tools and cleaned before doing the repair.

BELZONA FACTS

Belzona was cheaper and less time consuming than to replace the old concrete and drain

INDUSTRY

Buildings & Structures

LOCATION

Columbia TN

APPLICATION DATE

August 2024

PRODUCTS

Belzona 4111 (Magma-Quartz)
Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

- 1. Drain condition before repair with Belzona
- 2. Drain condition before repair with Belzona
- 3. Final application of Belzona solution
- 4. Final application of Belzona solution

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

