

BASF PLATE BOND ON HOPPER

ID: 9707



PROBLEM

Hopper had developed a worn area as was losing product.

APPLICATION SITUATION

Customer chose repairing over replacing the hopper.

APPLICATION METHOD

Plate was cut to size and roughened, and hopper was also prepared using hand tools. Belzona 1111 was applied to both surfaces.

BELZONA FACTS

If not repaired hopper would have to be replaced at some point.

INDUSTRY

Chemical & Petrochemical

LOCATION

Sparta TN

APPLICATION DATE

July 2024

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Surface preparation in the plate
2. Surface preparation in the equipment
3. Application of Belzona 1111 on the plate
4. Plate bonding completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

