

CHRIST CHURCH CHILLER TUBE SHEET

ID: 9709



PROBLEM

Mechanical contractor pulled the heads and covers and discovered the heads were worn and needed to be replaced or repaired.

APPLICATION SITUATION

Belzona was a great solution for repairing and protecting from future damage and wear.

APPLICATION METHOD

Mechanical contractors removed the covers then our team blasted the heads and covers. The tube sheet face needed to be rebuilt with Belzona 1121 and coated with 1321. The covers were also coated with Belzona 1321.

BELZONA FACTS

Belzona was a great option, we saved the customer thousands of dollars repairing instead of replacing.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

Brentwood TN

APPLICATION DATE

September 2021

PRODUCTS

Belzona 1121 (Super XL-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Tube sheet section damaged.
2. Rebuilding and protection completed with Belzona 1121 and Belzona 1321.
3. Ends covers damaged.
4. Protection completed with Belzona 1321.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

