

BONNELL SUMP

ID: 9713



PROBLEM

Customer had a leaking sump and damaged concrete.

APPLICATION SITUATION

Customer has us to come in every December to recoat and add more areas in the plant.

APPLICATION METHOD

Contractor has to prepare the concrete and follow guidelines for air quality and confine space. Belzona 4111 was used to rebuild the concrete and Belzona 4341 to provide chemical resistance protection.

BELZONA FACTS

We are helping to keep the plant safe from leaks next to impossible to replace all of the sumps and troughs.

INDUSTRY

General Industry

LOCATION

Gordonsville TN

APPLICATION DATE

December 2024

PRODUCTS

Belzona 4111 (Magma-Quartz)
Belzona 4341 (Magma CR4)

SUBSTRATE

Concrete

PHOTOS

1. Application area.
2. Application in progress.
3. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

