

CONCRETE CHEMICAL TROUGH PROTECTION WITH BELZONA

ID: 9714



PROBLEM

Trough was damaged due to age and acid attack. Customer required a Belzona solution.

APPLICATION SITUATION

Customer needed a quick solution. Could not afford to replace concrete due to downtime .

APPLICATION METHOD

Contractor had to naturalize and clean concrete then repair before coating. They had to monitor the air quality. Belzona 1111 was used to rebuild the areas and Belzona 4341 to provide chemical resistance protection.

BELZONA FACTS

Customer has us to recoat and continue adding more projects every December.

INDUSTRY

General Industry

LOCATION

Gordonsville TN

APPLICATION DATE

December 2024

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 4341 (Magma CR4)

SUBSTRATE

Concrete

PHOTOS

1. Overview of repair area.
2. Overview after surface preparation was completed.
3. Application in progress.
4. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

