ATTRITOR REPAIR WITH BELZONA

ID: 9715

1

2

3

4

PROBLEM
Attritor brick was detreating needed a solution to add longer life to the equipment.

APPLICATION SITUATION
Customer needed to add more life to the equipment. It was suggested to use Belzona 9811 tiles for additional abrasion resistance and customer agreed.

APPLICATION METHOD
Equipment was cleaned Belzona 1511 was used to build up low areas and to bond in Belzona 9811 tiles. Belzona 1813 was used as the grout due to temperature requirements.

BELZONA FACTS
Customer is very pleased with the outcome. saved thousands of dollars not having to replace equipment .

INDUSTRY
Chemical & Petrochemical

LOCATION
Dalton GA

APPLICATION DATE
June 2024

PRODUCTS
Belzona 1511 (Super HT-Metal)
Belzona 1813
Belzona 9811

SUBSTRATE
Masonry

PHOTOS
1. Overview of repair area.
2. Overview of repair area.
3. Application of Belzona 9811 tiles (bonded with Belzona 1511).
4. Grout completed with Belzona 1813.

Copyright © 1952-2026 Belzona International Limited.