

BELZONA SUPERWRAP II RESTORES FUEL STORAGE TANK PIPELINE

ID: 9767



PROBLEM
Pipeline to storage tank was suffering from thin wall corrosion at the weld seam.

APPLICATION SITUATION
This repair was completed in 2 days ensuring a quick turnaround and return to service.

APPLICATION METHOD
Belzona Superwrap II 10-year compliant repair installed by the onsite Rezitech Services Team

BELZONA FACTS
Belzona SuperWrap II is a composite repair solution designed to restore strength to weakened or holed metallic substrates.

INDUSTRY
Oil & Gas

LOCATION
NSW Australia

APPLICATION DATE
September 2023

PRODUCTS
Belzona 1211 (E-Metal)
Belzona 1982 (SuperWrap II)

SUBSTRATE
Carbon steel

- PHOTOS**
- 1. Pipeline to storage tank.
 - 2. Surface preparation and weld seam rebuilt with Belzona 1212 E Metal
 - 3. Application of Belzona 9381 Reinforcement Tape
 - 4. Super Wrap II repair completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

