

BELZONA MEMBRANE TO THE RESCUE

ID: 979



PROBLEM

Water penetrating gutter joints due to weight of water on the joints. Owner required immediate repairs to prevent disruption to business.

APPLICATION SITUATION

Felt roof over hotel restaurant.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1 and RPA-6.

BELZONA FACTS

The customer was impressed with the fact that repairs were completed without causing a major disruption or noise to restaurant guests. The application was completed during the cold month of December.

INDUSTRY

Buildings & Structures

LOCATION

Hotel, Edinburgh, Scotland

APPLICATION DATE

December 2007

PRODUCTS

Belzona 3131 (WG Membrane)

SUBSTRATE

Felt

PHOTOS

1. View of the "tired" and uncoated roof
2. Area where water was penetrating
3. Completed gutter, the main problem area
4. Completed Belzona application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

