

REPAIRS TO FLATS BALCONIES AND WALKWAYS

ID: 9798



PROBLEM

After being approached on a safety issue, Belzona were asked to supply a solution to make good spalled concrete areas and provide a safe walkway to a number of flats in the Nottingham area

APPLICATION SITUATION

The contractor have carried out many applications since the early 1970s . All residents were given notice of mobilization and were kept in the loop during the project

A Site compound was established and all relevant H&S matters were considered and signed off by the main contractor

APPLICATION METHOD

All concrete repairs were prepared according to IFU and System Leaflet WPA4

Application to all damaged areas using Belzona 4911 and Belzona 4141 Belzona 3131 was applied to the walkways and stairs using Granogrip, blinded into the second coat to offer a full grip system

BELZONA FACTS

Other materials were considered, but the main client has had experience on very similar works with Belzona and it was decided to stay with a tried, tested and proven solution

INDUSTRY

Buildings & Structures

LOCATION

Nottingham

APPLICATION DATE

March 2025

PRODUCTS

Belzona 3131 (WG Membrane)
Belzona 4141 (Magma-Build)
Belzona 4911 (Magma TX Conditioner)
Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Masonry

PHOTOS

1. Balcony before application
2. Stairs before application
3. Stairs after application
4. Stairs after application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

