

IN-SITU BELZONA REPAIR TO DRYER ROLLER

ID: 98



PROBLEM

Collapse of bearing caused damage to the journal

APPLICATION SITUATION

Bearing journal on dryer roller of paper machine

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet MPT-2.

BELZONA FACTS

This application was completed in half a day whereas traditional repair would have involved dismantling of the machine and would have taken more than two days and associated loss of production. After 5 years, repair is still in service and the customer was totally satisfied.

INDUSTRY

Pulp & Paper

LOCATION

Paper Mill in France

APPLICATION DATE

May 1993

PRODUCTS

Belzona 1111

SUBSTRATE

Steel

PHOTOS

1. General view of the damaged drying roller journal
2. Former clamped in place
3. Former removed showing accurately rebuilt journal

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.