


BELZONA HOT OFF THE PRESS

ID: 980



PROBLEM

Large hole torn in the belt caused by a metal tool being dropped onto the belt.

APPLICATION SITUATION

Conveyor belt carrying rejected newspapers.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

Due to the nature of the customers business and the need for this particular belt to be running almost 24 hours a day seven days a week, it was impossible to replace the belt and would cost around £3000. Utilising the Belzona system it cost them around £40 in materials and they got the belt back up and running within 2 hours, in time for the next print run.

INDUSTRY

Pulp & Paper

LOCATION

Regional Newspaper, Leeds, UK

APPLICATION DATE

May 2007

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Damaged belt
2. Preparation in progress
3. Finished application, with customer admiring his work

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

