

BELZONA ELIMINATES TRIPPING HAZARDS AT A MEDICAL FACILITY

ID: 9804



PROBLEM

An uncomfortable step was creating serious problems on the transition from rooms to bathrooms at a healthcare facility. The patients were tripping at a serious pace. Belzona came to the rescue.

APPLICATION SITUATION

The medical facility had references of similar jobs completed at other facilities and were looking for a permanent solution.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet FPA-1. After removing existing tripping hazard and excavating to create a solid foundation, Belzona 4131 was used to fill the space. Then, Belzona 4411 was used to complete a smooth transition.

BELZONA FACTS

Belzona products and know-how procedures have proven to perform excellently. The medical facility didn't want to keep dealing with these issues every other year. 13 transitions were created with the Belzona system for this project on first floor. There are four floors more to complete.

INDUSTRY

Buildings & Structures

LOCATION

West Palm Beach

APPLICATION DATE

March 2025

PRODUCTS

Belzona 4131 (Magma-Screed)
Belzona 4411 (Granogrip)
Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Existing transition from room to bathroom.
2. Removal of tripping hazard and surface preparation.
3. A new transition created with Belzona 4131.
4. Belzona 4411 applied as topcoat.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

