

BELZONA LINING OF WATER TANK

ID: 983



PROBLEM

Over a period of years the interior lining of the tank had deteriorated to a point where it was both leaking and affecting the water quality.

APPLICATION SITUATION

Company involved in manufacture of Margarine. As part of this process they use water drawn from a Bore Hole which is stored in a steel tank with a capacity 84,000 litres

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

Belzonas ability to provide a turn key solution through an Authorised contractor and approved materials within a very tight time frame won the business.

INDUSTRY

General Industry

LOCATION

Food manufacturer, UK

APPLICATION DATE

September 2007

PRODUCTS

Belzona 5811DW (DW Immersion Grade) Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Tank showing method for disposing of waste and debris from within tank
2. Top of Tank showing Hoist for vacuation of material and personnel
3. Internal of Tank prior to Coating
4. Internal of Tank after coating

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

