


BELZONA 4111 FOR REBUILDING STAIRS

ID: 9857



PROBLEM

The concrete on these steps was completely worn posing a dangerous work environment

APPLICATION SITUATION

This facility needed safer access to various parts of their facility and replacement wasn't an option.

APPLICATION METHOD

The application area was mechanically ground, Belzona 4911 applied and then Belzona 4111 applied providing a long term solution.

BELZONA FACTS

Belzona was used in lieu of replacement.

INDUSTRY

Commercial Facilities

LOCATION

Dayton, OH

APPLICATION DATE

August 1984

PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Picture of the problem area
2. Cleaned and applying Belzona 4911 (TX-Conditioner)
3. Belzona 4111 (Magma Quartz) being trowel applied
4. Finished!

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

