

BELZONA REPAIRS HEAVY TRAFFIC CONCRETE FLOOR

ID: 9878



PROBLEM

An area just inside the main roller door entrance, to a busy engineering works, experienced heavy traffic from forklifts, delivery vans and lorries. Over a period of time, the concrete slab gave up and started to disintegrate under the pressure of the traffic

APPLICATION SITUATION

This was the 5th attempt at repairing this area. It was proving extremely problematic for the Chief engineer and the staff who work in that area. The Engineer wanted to fix it with something "high-end" and durable, as repeat downtime and risk of trips, stumbles and falls, as well as damage to fork trucks were all issues that had to be rectified

APPLICATION METHOD

Remove loose and friable

Vacuum area

Mask up border lines

Mix and apply Belzona 4911 (TX Conditioner) to target areas

Mix and apply Belzona 4131 (Magma-Screed) with a gloved hand and compress to finish using a finishing trowel

BELZONA FACTS

After 5 failed attempts, the work was checked on after 6 months. No defects were found, apart from minor cracking to the concrete adjacent to the repair. The interface is still intact and the small cracks are in the parent concrete due to movement in the area. The repair remains solid, flat, level and safe. The Engineer is now attracting a price from a Belzona Experienced Contractor to pursue all the other areas of damage

INDUSTRY

General Industry

LOCATION

Mansfield

APPLICATION DATE

July 2024

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Part of the main repair, a previous application failed after only 6 weeks. This was their fourth attempt at repairing this floor area
2. Old, loose concrete and failed repair, no further excavation required. Area coated with Belzona 4911 (TX Conditioner)
3. Application of Belzona 4131 completed by the company's own staff, under supervision of the Belzona Area Sales Engineer
4. Shown here, in every day use, some 6 months on

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

