


HISTORICAL MARKER REPAIR WITH BELZONA 7311

ID: 9889



PROBLEM

This historical sign for a local graveyard dating back to the 1800's was struck by a vehicle that ran off the road. The vehicle struck the sign causing it to break into two separate pieces.

APPLICATION SITUATION

By using Belzona 7311 we saved this client a few thousand dollars. This sign was basically unrepairable to the client and to have another one made would have cost up to \$3000.00. And got the sign repaired and returned to the Client in less than a week where a replacement would've taken several months to manufacture.

APPLICATION METHOD

We first cleaned the surface using Belzona 9111. After cleaning we prepped the surface area using an MBX tool to scarify the surface. Once we had the surface cleaned and prepared for the 7311 we lined up each piece to trial fit them together. Once we were confident in lining them up we applied thin coat of 7311 to each piece. Then clamped them together and let them sit over night for 14 hours.

BELZONA FACTS

Cost savings for this application was \$3000

Only alternative to this repair was to have new sign approved by the Alabama Historical Commission and made.

INDUSTRY

General Industry

LOCATION

Guntersville, AL

APPLICATION DATE

October 2024

PRODUCTS

Belzona 7311

Belzona 9111F

SUBSTRATE

Cast Iron

PHOTOS

1. The signage was broken.
2. Belzona 7311 was used to repair the damage.
3. Both halves of the signage being clamped together for improved adhesion.
4. Finished application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

