

HI CHEM PUMP FEET PROTECTION

ID: 9897



PROBLEM

The Pump base was being eaten up by a combination of chemicals in their system in only 3 months.

APPLICATION SITUATION

The pump basis had to be done on-site at the customers premises. Belzona was the only option for them.

APPLICATION METHOD

Blasting, hand application

BELZONA FACTS

The pump basis has not been for several months

INDUSTRY

General Industry

LOCATION

Oklahoma city

APPLICATION DATE

March 2025

PRODUCTS

Belzona 4311 (Magma CR1)

SUBSTRATE

Carbon steel

PHOTOS

1. Pump pedestals being blasted
2. Pump pedestals first coat with Belzona 4311
3. Pump pedestals Close up first coat
4. Pump pedestals second coat

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

