


BELZONA REPAIRS HOSPITAL SHOWER

ID: 9927



PROBLEM

Patient rooms shower floors leaking

APPLICATION SITUATION

Patient shower floor was leaking when showers were being used. This was causing ceiling tile to be wet on the floor beneath and causing bacteria and having to close patient rooms. Belzona was as ample to do two rooms and release them back in 24 hours.

APPLICATION METHOD

Application was prepped by angle grinder with diamond ad with dust collector. Wiped down with cleaner, degreaser. Applied two coats of Belzona 5815 according to IFU incorporating aggregate.

BELZONA FACTS

Belzona was able to do two different showers and release the to be used in 24 hours. The competition was say three to four days.

INDUSTRY

Buildings & Structures

LOCATION

Lafayette

APPLICATION DATE

June 2025

PRODUCTS

Belzona 5815

Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Masonry

PHOTOS

1. Shower floor before
2. Shower floor during surface preparation
3. Shower floor after completion

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

