

BELZONA ROOF APPLICATION STILL WATERTIGHT 20 YEARS ON

ID: 993



PROBLEM

Water was leaking in, staining wallpaper, ceiling tile and carpet causing an obvious unsightly mess.

APPLICATION SITUATION

Parapet wall joints on visitors center leaking. Previous attempts with silicone sealant failed quickly.

APPLICATION METHOD

Application carried out in accordance with the Belzona Know-How System Leaflet RPA-10.

BELZONA FACTS

Labor costs of applying silicone sealant, which did not work, far exceeded the cost of the Belzona application. 20 years later, no leaks!

INDUSTRY

Buildings & Structures

LOCATION

Auto manufacturer, Wentzville, MO

APPLICATION DATE

October 1988

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Exposed aggregate concrete

PHOTOS

1. Belzona 3911 being applied
2. Belzona 3111 application
3. Follow up picture February 2008

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.