

BELZONA FLOOR REPAIR 24 YEARS ON

ID: 994



PROBLEM

Rough area caused vehicles to lose their load, creating a safety hazard and damage to package contents. In addition, the rough ride damaged sensitive electronic equipment.

APPLICATION SITUATION

Floor in front of highly trafficked overhead doorway leading to production area. Work had to be carefully scheduled so as not to impede constant traffic flow.

APPLICATION METHOD

Application was carried out in accordance with the Belzona Know-How System Leaflet FPA-1. Application was carried out in two halves so as not to disrupt constant traffic flow.

BELZONA FACTS

Safety concerns were paramount. One single piece of damaged electronics far surpassed the cost of the entire Belzona application. After 24 years, there is some slight damage, but the floor is still performing satisfactorily.

INDUSTRY

Buildings & Structures

LOCATION

Auto manufacturer, Wentzville, MO

APPLICATION DATE

Summer 1984

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Original floor in 1984
2. Belzona 4111 application completed
3. Belzona 4111 in February 2008

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

