


HIGH VISIBILITY MARKING FOR FALL HAZARD

ID: 9942



PROBLEM

The customer recognized a safety hazard atop wastewater tanks. When workers are present they must walk atop these tanks and the potential to trip and fall could result in a 4-5M fall. High visibility line markings were needed

APPLICATION SITUATION

Belzona BC has a long standing history of success with the plant and our products are recognized as the #1 choice for such applications.

APPLICATION METHOD

The areas were masked off in neat and tidy lines and a template was made indicating 'FALL HAZARD' as specified by the safety teams. Belzona 5231 was applied by brush and roller and Belzona 9231 Surefoot Aggregate was broadcasted to rejection. A final coat of Belzona 5231 was applied as a top coat.

BELZONA FACTS

Competitor high visibility products had previously been applied and lasted less than ONE year.

INDUSTRY

Water / Wastewater

LOCATION

Victoria, BC

APPLICATION DATE

June 2025

PRODUCTS

Belzona 5231 (SG Laminate)

Belzona 9231 (Surefoot Aggregate)

SUBSTRATE

Composite

PHOTOS

1. High visibility markings identifying fall hazard
2. Clean lines, 3 coats total were applied
3. Text application using custom stencil
4. A total 7 tank lids were completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

