

BELZONA PROTECTS CONTAINMENT AREA IN A WASTEWATER PLANT

ID: 9947



PROBLEM

A recent leak in the containment area had water penetrating through cracks in the concrete into an electrical room below.

APPLICATION SITUATION

A flexible coating was needed to bridge cracks and provide long term protection

APPLICATION METHOD

The concrete was ground using diamond cup grinders with hepa-vac systems. Two coats of Belzona 5815 were applied by brush & roller.

BELZONA FACTS

As the trusted coating supplier / contractor for the plant, Belzona was chosen from past successes in the plant.

INDUSTRY

Water / Wastewater

LOCATION

Victoria, BC

APPLICATION DATE

June 2025

PRODUCTS

Belzona 5815

SUBSTRATE

Concrete

PHOTOS

1. Photo of containment area with storage tanks removed
2. Application in progress
3. View of containment area
4. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

