

PUMP BASE REPAIR & COATING WITH BELZONA

ID: 9974



PROBLEM

The concrete pump base had water running over it for several years due to constant water running over the pump to keep it from over heating. The water had been eroding the concrete for many years. They were facing the replacement of two pump bases.

APPLICATION SITUATION

Cost savings is undetermined due to the trust the customer has in the Belzona product, they did not entertain the option to demo and rebuild a new pump base. The cost to repair the concrete and coat the bases for protection was only around three thousand dollars.

APPLICATION METHOD

We used needle guns to prepare the surface area. Once the surface was prepared we then cleaned the concrete using a vacuum to remove dust and small debris and MEK to clean the surface.

BELZONA FACTS

The customer saved several thousand dollars relying on Belzona to repair and coat the pump bases. The only alternative was to demolish the concrete bases and re-pour new bases.

INDUSTRY

Chemical & Petrochemical

LOCATION

Decatur, AL

APPLICATION DATE

July 2025

PRODUCTS

Belzona 4111 (Magma-Quartz)
Belzona 5821

SUBSTRATE

Concrete

PHOTOS

1. Before Belzona concrete repair and coating picture
2. Damaged area on side of pump base.
3. Repaired crack area on side of pump base using Belzona 4111
4. Completed repair and coating of concrete pump base using Belzona 4111 and Belzona 5821

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.